



SAAB AB EASA DOA 21J.066
EASA STC BY TYPE –
SITE NYKÖPING
 Effective date 2024-05-17

Ref
-
Sheet
1 (2)

SUPPLEMENTAL TYPE CERTIFICATE LOG

STC Number	Reference	Issue	Description	Applicable Aircraft	Approval date
Beech (Textron Aviation) (Former Hawker Beechcraft, Beechcraft Aircraft Corporation)					
EASA.A.S.02550 EASA STC 10014488 REV. 2	TDM06-04	A	Introduction of BRNAV and TAWS Class B.	Beech A100	2023-12-07
EASA STC 10063774 REV. 2	TDM17-24	C	Installation of SATCOM using Iridium satellites model: Flightcell DZMx.	TEXTRON AVIATION INC. Type: A100, 200, 300, 1900	2023-12-07
EASA STC 10069824 REV. 2	TDM19-05	D	Installation of SATCOM system Flightcell DZMx with Cabin Intercom/ Attendant Call	TEXTRON AVIATION INC. Type: A100, 200, 300, 1900 Model: B200GT	2023-12-07
FAA STC SA04461NY	TDM19-05	A	Installation of SATCOM system Flightcell DZMx with Cabin Intercom/ Attendant Call	TEXTRON AVIATION INC. Type: A100, 200, 300, 1900 Model: B200GT	2020-02-25
Casa 212					
EASA.A.S.00480 EASA STC 10082750 REV. 2	TDM04-14	4	ACAS II (Collins TCAS 4000) and dual Mode S Transponders. (Collins TDR-94).	CASA C-212	2023-09-12
EASA.A.S.00694 EASA STC 10082754 REV. 2	TDM04-18	D	ACAS II (Honeywell TCAS 2000) and single Mode S Transponder. (L-3 ACSS).	CASA C-212	2024-04-09
EASA STC 10082751 REV. 3					
EASA STC 10038972 REV. 2	TDM10-05	K	New Cabin Layout for Maritime Surveillance System in Casa C-212	CASA C-212	2023-09-12
Cessna					
EASA.A.S.03192 EASA STC 10014936 REV. 2	TDM07-18	C	Replacement of Mode S Transponders in Cessna 560 to comply with Enhanced Surveillance.	Cessna 560	2024-04-09
EASA STC 10014936 REV. 3					
EASA.A.S.03193 EASA STC 10014937 REV. 2	TDM07-19	B	Replacement of Mode S Transponders in Cessna 650 to comply with Enhanced Surveillance.	Cessna 650	2024-04-09
EASA STC 10014937 REV. 3					
Eurocopter					
EASA STC 10033697 REV. 1	TDM08-30	D	Installation of provisions for the New TopEye Mission Box to be mounted on the structure of the Under Carriage of AS355 as a variant to TopEye Laser Altimetry Pod.	Eurocopter AS355	2023-10-25
Learjet					
EASA.A.S.00255 EASA STC 10083410 REV. 1	TDM03-17	8	ACAS II 7.0 and 7.1. (Collins TCAS 4000) and dual Mode S Transponders (Collins TDR-94)	Learjet 35A	2023-12-06
EASA.A.S.01583 EASA STC 10014330 REV. 1	TDM03-03	D	Target Mission Operator's Console	Learjet 35A	2023-12-06
EASA.A.S.02582 EASA STC 10014508 REV. 1	TDM06-01	F	Mission Power and Electrical Cable Feed Thru in Baggage Floor.	Learjet 35A	2023-12-06



SAAB AB EASA DOA 21J.066
EASA STC BY TYPE –
SITE NYKÖPING
 Effective date 2024-05-17

Ref
-
Sheet
2 (2)

SUPPLEMENTAL TYPE CERTIFICATE LOG

STC Number	Reference	Issue	Description	Applicable Aircraft	Approval date
EASA.A.S.03465 EASA STC 10015116 REV. 2	TDM08-06	F	Installation of Honeywell MK VIII EGPWS in Learjet 35A with Mission Inhibit System.	Learjet 35A	2023-12-06
EASA.A.S.03532 EASA STC 10015162 REV. 1	TDM08-02	C	Mode S Enhanced Surveillance Upgrade.	Learjet 35A	2023-12-06
EASA STC 10053365 EASA STC 10053365 REV. 1	TDM14-48	A	ACAS II Honeywell CAS 67B Change 7.1	Learjet 35A	2023-12-06
EASA STC 10073509 EASA STC 10073509 REV. 1	TDM20-02	D	Installation of ADS-B out capability In Learjet 35A.	Learjet 35A	2023-12-06
LEONARDO S.p.A.					
EASA STC 10078618 EASA STC 10078618 REV. 1	TDM21-04	E	Inflation System for A109 Emergency Flotation System – Certification of a new inflation system as an alternative to the existing Moog’s inflation system.	LEONARDO S.p.A. Type: A109/A119 Model: A109A, A109AII, A109C, A109E, A109K2, A109LUH, A109N	2023-10-25
FAA STC SR00084IB	TDM21-04	D	Installation of Alternative Inflation System for Emergency Flotation System must be in accordance with Saab AB Master Data List Doc. No. TDM21-04-MDL, Issue D, dated November 7, 2022, or later EASA approved revisions.	LEONARDO S.p.A. Model: A109A, A109A II, A109C, A109K2, A109E	2022-12-19
Lockheed					
P-EASA.A.S.03618 SAP-0060004512 STC10031209-R1 STC10031209-R2 STC10031209-REV.-3 STC10031209 REV. 4 GACA/VAL-037 GACA/VAL-037 Rev. 1	TDM07-37	E	Installation of Saab Missile Protection System	Lockheed Martin L-382	2023-09-12 2011-01-30
MD Helicopters					
EASA STC 10057706 EASA STC 10057706 REV. 1	TDM14-30	B	Increase payload of Data Acquisition Module – Hardware, DAM-H, Vision Mount Module Installation.	MDH inc. MECAER AG SPA Type: D369, 500N, 600N, NH-AMD500 Model: 369D, 369E, 369H, 369HE, 369HM, 369HS, NH-500D	2023-10-25
Mitsubishi					
EASA.A.S.03472 EASA STC 10015123 REV. 2	TDM08-03	A	Garmin GTX330/330D upgrades for compliance with Enhanced Surveillance (EHS) requirements.	Mitsubishi MU-2B-20/-26	2023-12-07
EASA STC 10029935 EASA STC 10029935 REV. 2	TDM10-03	A	Installation Provisions/Video Signal in Mitsubishi MU-2B rear pressure bulkhead.	Mitsubishi MU-2B-20/-26	2023-12-07
EASA STC 10040413 EASA STC 10040413 REV. 2	TDM11-15	B	Installation of aft Pressure Bulkhead and Pressure feed Thru provisions for Antenna / Electrical Connectors	Mitsubishi MU-2B-20/-26	2023-12-07